



Ostrich 1300 Recommended Spares --- 1 Machine for 2 years

1. Potentiometer (108) 2 Nos.
2. GearBox (379)..... 1 No.
3. Cutting Torch (464) 1 No.
4. Fuses (110)..... 20 Nos.
5. Carbon Brushes (171)..... 10 Nos.
6. Resistor (107)..... 4 Nos.
7. Fibre Gear (176)..... 4 Nos.
8. Double Start Worm (173) 2 Nos.
9. Armiture (367) 1 No.
10. Centre off Switch (111) 1 No.
11. Magnet Rod Assembly (571).... 1 No.
12. Nut Nipples (148) 2 Nos.
13. Motor (573) 1 No.
14. Valve Box (466) 1 No.
15. Tracing Rollers (607) 10 Nos.
16. Half Nut (765) 1 No.
17. Magnet Coil (762)..... 1 No.
18. Diode Bridge (619) 1 No.
19. Magnet Push Button (763) 1 No.
20. Nozzles (149) as per work load.