



Ostrich 2000 Recommended Spares --- 1 Machine for 2 years

1. Potentiometer (108 ) ..... 2 Nos.
2. GearBox (379 )..... 1 No.
3. Cutting Torch ( 464 ) ..... 1 No.
4. Fuses ( 110 )..... 20 Nos.
5. Carbon Brushes ( 171)..... 10 Nos.
6. Resistor ( 107 )..... 4 Nos.
7. Fibre Gear (176 )..... 4 Nos.
8. Double Start Worm ( 173 ) .... 2 Nos.
9. Armiture ( 367 ) ..... 1 No.
10. Centre off Switch ( 111 ) ..... 1 No.
11. Magnet Rod Assembly ( 571).... 1 No.
12. Nut Nipples ( 148 ) ..... 2 Nos.
13. Motor ( 573 ) ..... 1 No.
14. Valve Box ( 466 ) ..... 1 No.
15. Tracing Rollers ( 607 ) ..... 10 Nos.
16. Half Nut ( 765 ) ..... 1 No.
17. Magnet Coil ( 762 )..... 1 No.
18. Diode Bridge ( 619 ) ..... 1 No.
19. Magnet Push Button ( 763 ) ..... 1 No.
20. Nozzles ( 149 ) ..... as per work load.